



C A R B 0887

Date : 26th August 2022

ANNEXURE - II

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/ Rear	90/90-12, 54L, 3.00-12, 63B, 3.75-12, 66B		Ralson
			3.75-12, 66B		Poddar Tyres
		Front/ Rear	3.75-12, 60J		Platinum, TVS
			90/90-12, 54J		TVS , Speedways, Innovative
		90/90-12, 64B, 3.75-12, 60J	CEAT		
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref. ANNEXURE-IB		IS:2553-Part 2-1992	
101	(1)	Windscreen Wiper		-	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Installation		IS 15796:2008	
		Limit :	83 dB(A) to 112 dB(A)		
		Observed :	101.5 dB(A)		
		Performance		IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-1)Rev.1:2011	
			Installation	AIS-002 (Part-1)Rev.1:2011	

ICAT Ref No.	2022-0687 (IOCS: 159545)
Power Test Report No.	CT0PR 0934 dt. 29.07.2022
Horn Inst. Report No.	CT0VO 0928 dt. 19.09.2019

AUTHORISED SIGNATORY				
VIJAYANTA AHUJA DEPUTY GENERAL MANAGER				