



C A R N 0952

Date : 15th September 2022

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard | |
|----------|--|---|-------------------|-------------------------------|-------------|
| 93 | (1A), (1B), (2) & (3) | Motor Vehicle width, length & height | | - | |
| 94 | (1), (2) & (3) | Condition of tyres | | - | |
| 95 | (1), (2),(3), (4), (5), (6) & (7) (Tubeless, Radial & Run-Flat) | Size & ply rating of tyres | | IS-15633:2005 & AIS-110:2009 | |
| | | Front | 235/55 R18 100 V | | Continental |
| | | Rear | | | |
| | | Temporary Use Spare Wheel | T125 70 R18 100 M | | Zhongce |
| | (8) | Tyre pressure monitoring system | | AIS 154 : 2018 | |
| 96 | (1), (2), (3), (4)(ii), (4B), (7)(a) & (8) | Brakes | | IS-15986:2015 | |
| | (10) | Electronic Stability Control | | AIS 133:2016 | |
| | (11) | Brake assist System | | AIS 152:2018 | |
| 96B | (a) & (b) | High Speed Brake Requirements | | IS-15986:2015 | |
| 98 | (3) | Steering gear | | IS-11948:2010 | |
| | (1), (2) | | | IS-12222:2011 | |
| 99 | - | Forward and backward motion | | - | |
| 100 | (1), (2), (3) & (3c) | Safety glass | | IS 2553 (Part 2)(Rev.1) :2019 | |
| 101 | (1) & (2) | Windscreen wiper | | IS-15804:2008 | |
| 102 | (1) & (2) | Signalling devices, direction indicators and stop lights | | - | |
| 103 | (1) & (2) | Position of the indicator | | - | |
| 104 | (1) & (4) | Fitment of reflectors | | AIS-057 (Rev. 1): 2010 | |
| 105 | (1) (a), (2), (3), (4) & (7) | Lamps | | - | |
| 106 | (1) | Deflection of lights | | - | |
| 108 | (1) | Use of red or white lights | | - | |
| 109 | - | Parking light | | - | |
| 111 | - | Prohibition of spotlights etc. | | - | |
| 112 | - | Exhaust gases | | - | |
| 113 | - | Location of exhaust pipes | | - | |
| 115 | (1), (2)(i), 18(i) | Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD I & OBD II)) | | AIS-137 | |
| 115G | (1) & (2) | Fuel Consumption Standard | | - | |
| 117 | (1) & (2) | Speedometer | | IS-11827:2008 | |
| 118 | (1) | Speed Governor | | NA | |

| | | | |
|-----------------------|--------------------------------|----------------|---------------------------|
| ICAT Ref No. | 2022 - 0942 [IOCS No.: 159025] | | |
| Emission Report No. | CT0PR 1025 DT. 13.09.2022 | | |
| Noise Report No. | CT0VR 1244 dt. 09.09.2022 | | |
| Horn Inst. Report No. | CT0VN 0515 dt. 23.03.2018 | FTP Report No. | CT0ER 0333 DT. 17.08.2022 |

| | | | |
|--|--|---|--|
| AUTHORISED SIGNATORY | | | |
| | | | |
| VIJAYANTA AHUJA DEPUTY GENERAL MANAGER | | PAMELA TIKKU DIRECTOR (Offg.) | |
| | | | |
| | | Page 2 of 6 | |