



C A Q B 1031 V02




Date : 21st September 2022

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Front	110/70-17, 54P	M/s. Ralson	IS 15627:2005 & AIS-050:2004
		Rear	140/70-17, 66S		
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		109.2 dB(A)
			Performance	IS 1884:1993	
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed :	66 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Hand hold	IS 14495:1998	
	(2)		Footrests	AIS 148:2018	
	(4)		Stand	AIS 146:2018	
	(5)		External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2022-0903 (IOCS Ref: 160067)
Power Test Report No.	CT0EQ 0254 dt. 27.07.2021
Noise Report No.	CT0VQ 1373 dt. 10.11.2021
Horn Inst. Report No.	CT0VQ 1374 dt. 10.11.2021

AUTHORISED SIGNATORY

		
VIJAYANTA AHUJA DEPUTY GENERAL MANAGER	PAMELA TIKKU DIRECTOR	

Page 2 of 4