






C A R B 0973

Date : 23rd September 2022

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Front / Rear Tube Type)	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050:2004	
		4.5-10, 84E 8PR	M/s. Ralco		
		4.5-10, 85E 8PR	M/s. Zahi Tyres (Ceat) M/s Braza		
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes		IS 14664:2010	
98	(1), (2) & (3)	Steering gear		NA	
99	---	Forward and backward motion		-	
100	(1), (2) & (3)	Safety glass		NA	
101	(1) & 2(iii)	Windscreen wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	1(v) & (4)	Fitment of reflectors & Reflective tapes		AIS-057 (Rev. 1): 2010 & AIS:090-2005	
105	(1)(b), (3),(4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	---	Parking Lights		-	
110	---	Lamps on 3 Wheelers		AIS-134:2016	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7 Kw)	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		101.7 dB(A)
			Performance	IS 1884:1992	
120	(2)	Pass by Noise	Limit :	77 dB(A)	
			Observed :	69 dB(A)	
ICAT Ref No.		2021-2180 (IOCS: 156510)			
Power Report No.		CT0PR 0502 dt. 29.03.2022			
Noise Report No.		CT0VR 0745 dt. 01.06.2022			
Horn Inst. Report No.		CT0VR 0746 dt. 01.06.2022			

AUTHORISED SIGNATORY

		
<p>VIJAYANTA AHUJA DEPUTY GENERAL MANAGER</p>	<p>PAMELA TIKKU DIRECTOR (offg.)</p>	<p>Page 4 of 4</p>