







C	A	R	B	1026
---	---	---	---	------

Date : 14th October 2022

ANNEXURE - II

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		 IS 15627:2005 & AIS-050-2004	
		Front/ Rear	90/90-12, 54J		Speedways
			3.75-12, 54L		Ralson
			3.75-12, 66 B		CEAT
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref. ANNEXURE - IB		IS:2553-Part 2-1992	
101	(1)	Windscreen Wiper		-	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	86.9 dB(A)	
			Performance		IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications		AIS-001 (Part-1)Rev.1:2011
		Mirror	Installation		AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2021-2215 (IOCS: 156584)
Power Test Report No.	CT0PR 0646 dt. 14.05.2022
Horn Inst. Report No.	CT0VR 1424 dt. 14.10.2022
AUTHORISED SIGNATORY	
 VIJAYANTA AHUJA DEPUTY GENERAL MANAGER	 PAMELA TIKKU DIRECTOR (Offg.)
	 Page 2 of 3