



C A R B 1131

Date : 23<sup>rd</sup> November 2022

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/ Rear	3.75-12, 60 J 90/90-12, 54E		Platinum Rubber
			90/90-12, 54L		Ram Lubhaya & Sons
			3.75-12, 60 J 90/90-12, 54J		TVS
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref. ANNEXURE - IB		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit : 83 dB(A) to 112 dB(A)		
			Observed : 96 dB(A)		
		Performance	IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-2) Rev.1:2011	
			Installation	AIS-002 (Part-2) Rev.1:2011	

ICAT Ref No.	2022-0991 (IOCS: 160471)
Power Test Report No.	ARAI/AED/CT/OC-1617-8917/227 dt. 26.05.2017
Horn Inst. Report No.	ARAI/SHL/CT/APX-1617-15211/801 dt. 03.03.2017

<b>AUTHORISED SIGNATORY</b>				
<b>VIJAYANTA AHUJA</b> <b>DEPUTY GENERAL MANAGER</b>	<b>PAMELA TIKKU</b> <b>DIRECTOR (Offg.)</b>			
				Page 2 of 3