



<b>C</b>	<b>A</b>	<b>R</b>	<b>B</b>	<b>1180</b>
----------	----------	----------	----------	-------------

Date : 08<sup>th</sup> December 2022

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/ Rear	Make		CEAT
			90/90-12, 54J 3.75-12, 66B		
3.75-12, 60 J 90/90-12, 54J	TVS				
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref: ANNEXURE-IB		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		96.2 dB(A)
			Performance	IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-2) Rev.1:2011	
			Installation	AIS-002 (Part-2) Rev.1:2011	

<b>ICAT Ref No.</b>	2022-0547 (IOCS: 159047)
<b>Power Test Report No.</b>	CT0PR 0959 dt. 09.08.2022
<b>Horn Inst. Report No.</b>	CT0VR 1438 dt. 15.10.2022

<b>AUTHORISED SIGNATORY</b>			
<b>VIJAYANTA AHUJA</b> DEPUTY GENERAL MANAGER	<b>SAURABH DALELA</b> DIRECTOR		
			Page 2 of 3