



C	A	Q	N	0091	F01
---	---	---	---	------	-----



Date : 06th January 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor Vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (1A), (2), (3), (4), (5), (6) & (7) (Tubeless & Radial)	Size & ply rating of tyres		IS-15633:2005, AIS-051:2004, AIS-142:2019	
		Front / Rear	1. 165/70 R14 81S 2. 175/60 R15 81H		1. Bridgestone 2. Yokohama
		Spare Wheel	165/70 R14 81S		Bridgestone
		Temporary Spare Wheel	175/60 R15 81H		Yokohama
(8)	Tyre pressure monitoring system		NA		
96	(1), (2), (3), (4)(ii), (4B), (7)(a) & (8)	Brakes		IS-15986:2015	
	(10)	Electronic Stability Control		AIS-133:2016	
	(11)	Brake assist System		AIS-152:2018	
96B	(a) & (b)	High Speed Brake Requirements		IS-15986:2015	
98	(3)	Steering gear		IS-11948:2010	
	(1), (2)			IS-12222:2011	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2)(Rev.1) :2019	
101	(1) & (2)	Windscreen wiper		IS-15804:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(i), 18(i)	Emission of smoke, vapour, etc. from motor vehicle		AIS-137	
115G	(1) & (2)	Fuel Consumption Standard		AIS-137	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor		NA	

ICAT Ref No.	2022-1541 [IOCS No: 162734]
Emission Report No.	CT0PQ 0256 dt.03.02.2021 & CT0PR1208 dt. 21.12.2022
Noise Report No.	CT0VQ 0042 dt. 14.01.2021
FTP Report No.	CT0EQ 0023 dt. 29.01.2021
Horn Inst. Report No.	CT0VQ 0043 dt. 14.01.2021

AUTHORISED SIGNATORY

	
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR