



C	A	R	B	0078	V04
---	---	---	---	------	-----

Date : 06<sup>th</sup> January 2023

## ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004
		Front/ Rear	90/90-12, 54L	M/s RALCO	
		90/90-12, 54J		M/s CEAT	
		90/90-12, 54L		M/s BRAZA	
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signalling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	86.2 dB(A)	
		Performance			IS 1884:1993
120	(2)	Pass by Noise	Limit :	74 dB(A)	IS 3028:1998
			Observed	59 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
	(2)			Footrests	AIS 148:2018
	(4)			Stand	AIS 146:2018
	(5)			External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part 2) (Rev.1):2011
			Installation		AIS-002 (Part 2) (Rev.1):2011

ICAT Ref No.	2022-1644 (IOCS Ref: 163136)
Power Test Report No.	CTOPQ 0825 dt. 18.10.2021
Noise Report No.	CTOVQ 1515 dt. 21.12.2021
Horn Inst. Report No.	CTOVQ 1516 dt. 21.12.2021

AUTORISED SIGNATORY		INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY <b>ICAT</b> Innovation • Service • Excellence MANESAR	SAURABH DALELA DIRECTOR	Page 2 of 4
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER				