



**C A S B 0021**

**Date : 06<sup>th</sup> January 2023**

**ANNEXURE - I**

<b>Rule No.</b>	<b>Sub Rule(s)</b>	<b>Compliance Verified For</b>			<b>Standard</b>		
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-		
94	(1), (2), (3)	Condition of tyres			-		
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004		
		Front/Rear	3.75-12, 66 B	CEAT			
		Front/Rear	3.75-12, 54L	Ralson			
			90/90-12, 54J	Speedways			
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999		
99	-	Forward and backward motion			-		
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref: ANNEXURE - IB			NA		
101	(1)	Windscreen Wiper			NA		
102	(1), (2)	Signaling devices, direction indicators and stop lights			-		
103	(1), (2)	Position of the indicator			-		
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057-2005 & AIS-090-2005		
105	(1)(b), (3), (4), (5), (7)	Lamps			-		
106	(1)	Deflection of lights			-		
108	(1)	Use of red or white lights			-		
109	-	Parking lights			-		
110	-	Lamps for three wheelers			-		
111	-	Prohibition of spotlights etc.			-		
119	(1) & (2)	Horns	Installation		IS 15796:2008		
			Limit :	83 dB(A) to 112 dB(A)			
			Observed :	95.3 dB(A)			
			Performance		IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005		
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB		
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011		
			Installation		AIS-002 (Part-2)Rev.1:2011		

<b>ICAT Ref No.</b>	2022-1018; (IOCS: 160549)
<b>Power Test Report No.</b>	CTOPR 1119 dt. 15.11.2022
<b>Horn Inst. Report No.</b>	CT0VM 1991 dt. 28.11.2017

<b>AUTHORISED SIGNATORY</b>		
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	 <b>MANESAR</b>	Saurabh Dalela DIRECTOR
		Page 2 of 3