



**C | A | S | N | 0152**

**Date : 15<sup>th</sup> February 2023**

**ANNEXURE - I**

<b>Rule No.</b>	<b>Sub Rule(s)</b>	<b>Compliance Verified For</b>				<b>Standard</b>
93	(1)(A), (1)(B), (2) & (3)	Motor Vehicle width, length and height				-
94	(1), (2) & (3)	Condition of tyres				-
95	(1), (2),(3), (4), (5) & (6) (Tubeless / Radial)	Size & ply rating of tyres			Make	IS-15633:2005, AIS-051:2004
		Front / Rear / Spare	17"	265/65R17 112S	Bridgestone	
	(7)	Temporary Use Spare Wheel				NA
96	(1), (2),(3), (4)(ii), (7)(a) & (8)	Brakes				IS-11852:2013
	(10)	Electronic Stability Control (ESC)				AIS 133:2016
	(11)	Brake assist System (BAS)				AIS 152:2018
98	(3)	Steering gear				IS-11948:2010
	(1), (2)					IS-12222:2011
99		Forward and backward motion				-
100	(1), (2), (3) & (3c)	Safety glass				IS-2553 (Part 2):2019
101	(1) & (2)	Windscreen wiper				IS-15802:2008
102	(1) & (2)	Signalling devices, direction indicators and stop lights				-
103	(1) & (2)	Position of the indicator				-
104	(1)(i)	Fitment of reflectors				AIS-090:2005
	(4)					AIS-057 (Rev. 1): 2010
105	(1) (a), (2), (3), (4) & (7)	Lamps				-
106	(1)	Deflection of lights				-
108	(1)	Use of red or white lights				-
109	-	Parking light				-
111	-	Prohibition of spotlights etc.				-
114	(1) & (2)	Exhaust gases and exhaust pipes				-
115	(1), (2)(ii) & 18(i)	Emission of smoke, vapour, etc. from motor vehicle				AIS 137
115G	(1), (2)	Fuel Consumption Standard				NA
117	(1) & (2)	Speedometer				IS-11827:2008
118	(1)	Speed Governor (SLF in ECU)				AIS-018,2001

**ICAT Ref No.** [IOCS No. : 163492]

**Emission Report No.** CTOPS 0251 dt. 18.01.2023

**FTP Report No.** CT0EP 0244 dt. 15.06.2020

**Noise Report No.** CT0VR 0221 dt. 16.02.2022

**Horn Inst. Report No.** CT0VR 0223 dt. 16.02.2022

**AUTHORISED SIGNATORY**

<b>MADHUSUDAN JOSHI</b> <b>DEPUTY GENERAL MANAGER</b>	 <b>INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY</b> <b>MANESAR</b>	<b>SAURABH DALELA</b> <b>DIRECTOR</b>	 Toyota Motor Service & Excellence
			<b>Page 2 of 5</b>