



**C A L B 0178 F02**

**Date : 23<sup>rd</sup> February 2023**

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For	Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height	-	
94	(1), (2), (3)	Condition of tyres	-	
95	(1), (2),(3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres	IS 15627:2005 & AIS-050-2004	
		90/90-12 54J,3.75x12 60J		TVS
		3.75x12 66E		Apollo, JK Tyre
		90/90-12 64B		JK Tyre, CEAT, Apollo
		90/90-12 54L		RALSON
3.00x12 63B				
		3.75x12 66B	Ralson, CEAT, Poddar	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes	IS 14664:1999	
99	-	Forward and backward motion	-	
100	(1),(2),(3)	Safety glass as amended by GSR 784(E) – Ref. ANNEXURE-IB	NA	
101	(1)	Windscreen Wiper	NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights	-	
103	(1), (2)	Position of the indicator	-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes	AIS-057-2005 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps	-	
106	(1)	Deflection of lights	-	
108	(1)	Use of red or white lights	-	
109	-	Parking lights	-	
110	-	Lamps for three wheelers	-	
111	-	Prohibition of spotlights etc.	-	
119	(1) & (2)	Installation	IS 15796:2008	
		Limit :		83 dB(A) to 112 dB(A)
		Observed :		102.4 dB(A)
		Performance	IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)	AIS-065-2005	
124	-	Safety standards of components as applicable	Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View Mirror	Specifications	
		Installation	AIS-001 (Part-2)Rev.1:2011 AIS-002 (Part-2)Rev.1:2011	

**ICAT Ref No.** 2022-1744, (IOCS :163360)  
**Power Test Report No.** CT0PR 1212 Dt.26.12.2022  
**Horn Inst. Report No.** CT0VS 0064 Dt.13.01.2023

**AUTHORISED SIGNATORY**

**MADHUSUDAN JOSHI**  
**DEPUTY GENERAL MANAGER**

**SAURABH DALELA**  
**DIRECTOR**

Page 2 of 3

