





|   |   |   |   |      |
|---|---|---|---|------|
| C | A | S | B | 0193 |
|---|---|---|---|------|

Date : 23<sup>rd</sup> February 2023

## ANNEXURE - I

| Rule No. | Sub Rule(s)                                  | Compliance Verified For  |                               | Standard                     |
|----------|--|--|-------------------------------|------------------------------|
| 93       | (1)(A), (1)(B), (2)                          | Motor vehicle width, length and height   |                               | -                            |
| 94       | (1), (2), (3)                                | Condition of tyres   |                               | -                            |
| 95       | (1), (2), (3), (4), (5) & (6)<br>(Tube Type) | Size & ply rating of tyres   |                               | IS 15627:2005 & AIS-050-2004 |
|          |  | Front/<br>Rear   | Make                          |                              |
|          |  | 3.00-12,63B  | Ralson                        |                              |
|          |  | 3.75-12-60J  | TVS                           |                              |
| 96       | (1), (2), (3), (4)(i), (7)(b)                | Brakes   |                               | IS 14664:1999                |
| 99       | -  | Forward and backward motion  |                               | -                            |
| 100      | (1), (2), (3-A) & (3)(c)                     | Safety glass as amended by GSR 784(E) – Ref. ANNEXURE - IB   |                               | NA                           |
| 101      | (1)  | Windscreen Wiper   |                               | NA                           |
| 102      | (1), (2)                                     | Signaling devices, direction indicators and stop lights  |                               | -                            |
| 103      | (1), (2)                                     | Position of the indicator  |                               | -                            |
| 104      | (1)(v), (4)                                  | Fitment of reflectors & reflective tapes   |                               | AIS-057-2005 & AIS-090-2005  |
| 105      | (1)(b), (3), (4), (5), (7)                   | Lamps  |                               | -                            |
| 106      | (1)  | Deflection of lights   |                               | -                            |
| 108      | (1)  | Use of red or white lights   |                               | -                            |
| 109      | -  | Parking lights   |                               | -                            |
| 110      | -  | Lamps for three wheelers   |                               | -                            |
| 111      | -  | Prohibition of spotlights etc.   |                               | -                            |
| 119      | (1) & (2)                                    | Horns  | Installation                  | IS 15796:2008                |
|          |  |  | Limit : 83 dB(A) to 112 dB(A) |                              |
|          |  |  | Observed : 92.1 dB(A)         |                              |
|          |  |  | Performance                   | IS 1884:1993                 |
| 122      | (1) & (2)                                    | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) |                               | AIS-065-2005                 |
| 124      | -  | Safety standards of components as applicable   |                               | Refer ANNEXURE - IA & IB     |
| 125      | (2)(a)                                       | Rear View<br>Mirror  | Specifications                | AIS-001 (Part-2)Rev.1:2011   |
|          |  |  | Installation                  | AIS-002 (Part-2)Rev.1:2011   |

|   |                          |   |             |
|---|--------------------------|---|-------------|
| ICAT Ref No.  | IOCS : 159087            |   |             |
| Power Test Report No.   | CT0PM 0231 dt.19.04.2017 |   |             |
| Horn Inst. Report No.   | CT0VM 0836 dt.19.06.2017 |   |             |
| <b>AUTHORISED SIGNATORY</b>   |                          |   |             |
|  |                          |  |             |
|   |                          |   |             |
|   |                          |   | Page 2 of 3 |