



C A S B 0225

Date : 01<sup>st</sup> March 2023

## ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard		
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-		
94	(1), (2), (3)	Condition of tyres			-		
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004		
		Front/Rear	90/90-12, 64B	CEAT/ MRF			
		Front/Rear	90/90-12, 54L 3.00-12, 63 B	Ralson India Ltd.			
			90/90-12, 54J	Speedways/ Innovative			
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999		
99	-	Forward and backward motion			-		
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref: ANNEXURE - IB			NA		
101	(1)	Windscreen Wiper			NA		
102	(1), (2)	Signaling devices, direction indicators and stop lights			-		
103	(1), (2)	Position of the indicator			-		
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057-2005 & AIS-090-2005		
105	(1)(b), (3), (4), (5), (7)	Lamps			-		
106	(1)	Deflection of lights			-		
108	(1)	Use of red or white lights			-		
109	-	Parking lights			-		
110	-	Lamps for three wheelers			-		
111	-	Prohibition of spotlights etc.			-		
119	(1) & (2)	Horns	Installation		IS 15796:2008		
			Limit :	83 dB(A) to 112 dB(A)			
			Observed :	101.9 dB(A)			
			Performance		IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005		
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB		
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011		
			Installation		AIS-002 (Part-2)Rev.1:2011		

ICAT Ref No.	2022-1003; (IOCS: 160362)
Power Test Report No.	CTOPR 1010 dt. 05.09.2022
Horn Inst. Report No.	CTOVR 1731 dt. 12.12.2022

AUTHORISED SIGNATORY			
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY MANESAR	SAURABH DALELA DIRECTOR	Page 2 of 3