



C	A	S	B	0342
---	---	---	---	------

Date : 25th March 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-
94	(1), (2), (3)	Condition of tyres			-
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004
		Front/Rear	90/90-12 64B, 4PR	CEAT	
			3.75-12 66B, 4PR		
			3.00x12, 63B, 4PR	RALSON	
			3.75-12 66B, 4PR		
			90/90-12, 54J, 4PR	TVS	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999
99	-	Forward and backward motion			-
100	(1),(2),(3)	Safety glass as amended by GSR 784(E) – Ref: ANNEXURE - IA			NA
101	(1)	Windscreen Wiper			NA
102	(1), (2)	Signaling devices, direction indicators and stop lights			-
103	(1), (2)	Position of the indicator			-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057-2005 & AIS-090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
109	-	Parking lights			-
110	-	Lamps for three wheelers			-
111	-	Prohibition of spotlights etc.			-
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	97.7 dB(A)	
Performance			IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011
			Installation		AIS-002 (Part-2)Rev.1:2011

ICAT Ref No.	2022-1870,(IOCS :163826)
Power Test Report No.	CTOPS 0315 Dt.16.02.2023
Horn Inst. Report No.	CTOVS 0429 Dt.11.03.2023

AUTHORISED SIGNATORY				
		 MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER		
			SAURABH DALELA DIRECTOR	Page 2 of 3