



C A S B 0399

Date : 30th March 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004
		Front/ Rear	90/100-10, 53J	M/s RALCO	
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below-7kW)		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
120	(2)	Pass by Noise	Observed :	93 dB(A)	IS 1884:1993
			Performance		
121	(1) & (2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed	60 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
	(2)			Footrests	AIS 148:2018
	(4)			Stand	AIS 146:2018
	(5)			External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications Installation	AIS-001 (Part 2) (Rev.1):2011 AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2022-1963 (IOCS Ref: 164074)
Power Test Report No.	CTOPR 0894 dt. 18.07.2022
Noise Report No.	CTOVS 0570 dt. 29.03.2023
Horn Inst. Report No.	CTOVS 0575 dt. 29.03.2023

AUTORISED SIGNATORY		INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY ICAT Innovation • Service • Excellence MANESAR	SAURABH DALELA DIRECTOR	Page 2 of 4
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER				