



C A S N 0435

Date : 17<sup>th</sup> April 2023

## ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard			
93	(1)(A), (1)(B), (2) & (3)	Motor Vehicle width, length and height			-			
94	(1), (2) & (3)	Condition of tyres			-			
95	(1), (1A), (2), (3), (4), (5) & (6) (Tubeless & Radial)	Size & ply rating of tyres		Make	IS-15633:2005, AIS-051:2004 & AIS 142:2019			
		Front / Rear / Spare Wheel	195/80R15 96S	Bridgestone				
	(8)	Tyre pressure monitoring system			NA			
96	(1), (2), (3), (4)(ii), (4B), (7)(a) & (8)	Brakes			IS-15986:2015			
	(10)	Electronic Stability Control			AIS-133:2016			
	(11)	Brake assist System			AIS-152:2018			
96B	(a) & (b)	High Speed Brake Requirements			IS-15986:2015			
98	(3)	Steering gear			IS-11948:2010			
	(1), (2)				IS-12222:2011			
99	-	Forward and backward motion			-			
100	(1), (2), (3) & (3c)	Safety glass			IS 2553 (Part 2)(Rev.1) :2019			
101	(1) & (2)	Windscreen wiper			IS-15804:2008			
102	(1) & (2)	Signalling devices, direction indicators and stop lights			-			
103	(1) & (2)	Position of the indicator			-			
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010			
105	(1) (a), (2), (3), (4) & (7)	Lamps			-			
106	(1)	Deflection of lights			-			
108	(1)	Use of red or white lights			-			
109	-	Parking light			-			
111	-	Prohibition of spotlights etc.			-			
114	(1) & (2)	Exhaust gases and exhaust pipes			-			
115	(1), (2)(i), 18(i)	Emission of smoke, vapour, etc. from motor vehicle			AIS-137			
115G	(1) & (2)	Fuel Consumption Standard			AIS-137			
117	(1) & (2)	Speedometer			IS-11827:2008			
118	(1)	Speed Governor			NA			
ICAT Ref No.	2022-1871 [IOCS No. 162579]							
Emission Report No.	CT0PS 0405 dt. 09.03.2023 & CT0PS 0509 dt. 29.03.2023							
Noise Report No.	CT0VS 0450 Dt. 13.03.2023							
FTP Report No.	CT0ES 0116 dt. 01.02.2023							
Horn Inst. Report No.	CT0VS 0447 Dt. 13.03.2023							
AUTORISED SIGNATORY								
		 <b>INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY</b> <b>ICAT</b> <i>Innovation • Service • Excellence</i> <b>MANESAR</b>						
<b>MADHUSUDAN JOSHI</b> <b>DEPUTY GENERAL MANAGER</b>			<b>SAURABH DALELA</b> <b>DIRECTOR</b>					
 Page 2 of 6								