





C	A	S	B	0526
---	---	---	---	------

Date : 18th May 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard		
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-		
94	(1), (2), (3)	Condition of tyres		-		
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004		
		Front	90/90-12 54J		TVS	
			3.75x12 66E		Apollo, JK Tyre	
			90/90-12 64B		JK Tyre, CEAT, Apollo	
		Rear	90/90-12 54L, 3.00x12 63B		RALSON	
			3.75x12 66B		Ralson, CEAT, Poddar	
3.75x12 60J	TVS					
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999		
99	-	Forward and backward motion		-		
100	(1),(2),(3)	Safety glass		IS 2553(Part 2)(Rev.1):2019		
101	(1),(2)	Windscreen Wiper		IS 15802-2008		
102	(1), (2)	Signaling devices, direction indicators and stop lights		-		
103	(1), (2)	Position of the indicator		-		
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005		
105	(1)(b), (3), (4), (5), (7)	Lamps		-		
106	(1)	Deflection of lights		-		
108	(1)	Use of red or white lights		-		
109	-	Parking lights		-		
110	-	Lamps for three wheelers		-		
111	-	Prohibition of spotlights etc.		-		
119	(1) & (2)	Horns	Installation		IS 15796:2008	
			Limit :	83 dB(A) to 112 dB(A)		
			Observed :	88.9 dB(A)		
			Performance		IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005		
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB		
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011	
			Installation		AIS-002 (Part-2)Rev.1:2011	

ICAT Ref No.	2022-1911;(IOCS :164364)
Power Test Report No.	CT0PS 0554 Dt.30.03.2023
Horn Inst. Report No.	CT0VS 0660 Dt.13.04.2023

AUTHORISED SIGNATORY				
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER		SAURABH DALELA DIRECTOR		
			Page 2 of 3	