



C	A	S	B	0535
---	---	---	---	------

Date : 22nd May 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95 (1), (2), (3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050-2004
		3.75-12 66 B	CEAT	
		90/90-12, 54J	INNOVATIVE	
		90/90-12, 54J	SPEEDWAYS	
		90/90-12, 54L	RALSON	
		3.00-12, 63 B	RALSON	
96 (1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999
	Forward and backward motion			-
100	(1),(2),(3)	Safety glass		NA
101	(1),(2)	Windscreen Wiper		NA
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119 (1) & (2)	Horns	Installation		IS 15796:2008
		Limit :	83 dB(A) to 112 dB(A)	
		Observed :	101.7 dB(A)	
122 (1) & (2)		Performance		IS 1884:1993
				AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125 (2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011
		Installation		AIS-002 (Part-2)Rev.1:2011

ICAT Ref No.: IOCS : CBU_302

Power Test Report No.: CTOPS0366 Dt.01.03.2023

Horn Inst. Report No.: CT0VS0637 Dt.10.04.2023

AUTHORISED SIGNATORY

MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR	SAURABH DALELA DIRECTOR	 Page 2 of 3
--	--	----------------------------	--