



**C | A | R | B | 0990 | F01**

**Date : 31<sup>st</sup> May 2023**

**ANNEXURE - I**

<b>Rule No.</b>	<b>Sub Rule(s)</b>	<b>Compliance Verified For</b>		<b>Standard</b>
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front/ Rear	3.75-12, 66B	
			3.75-12, 54L	
			3.75-12, 66E	
			90/90-12, 54J	Speedways
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3-A) & (3)(c)	Safety glass as amended by GSR 784(E) – Ref: ANNEXURE- IB		NA
101	(1)	Windscreen Wiper		NA
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Installation		IS 15796:2008
		Horns	Limit :	
			83 dB(A) to 112 dB(A)	
		Observed :		IS 1884:1993
		101.9 dB(A)		
122	(1) & (2)	Performance		AIS-065-2005
		Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-2)Rev.1:2011
			Installation	
				AIS-002 (Part-2)Rev.1:2011

<b>ICAT Ref No.</b>	2023-0139 (IOCS: 166862)
<b>Power Test Report No.</b>	CTOPR 0283 dt. 09.02.2022
<b>Horn Inst. Report No.</b>	CT1VR 1359 dt. 04.10.2022

<b>AUTHORISED SIGNATORY</b>		
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	 <b>INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY MANESAR</b>	SARABH DALELA DIRECTOR
		Page 2 of 3