



C	A	K	B	0126	F01
---	---	---	---	------	-----

Date : 12<sup>th</sup> June 2023

## ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2),(3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front/	90/90-12 64B 3.75-12 66E	
		Rear	90/90-12 64B 3.75-12 66B	
			3.00-12, 63B, 90/90-12 54L	
			90/90-12 54J	
			90/90-12 54J 3.75-12 60J	
			TVS	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1),(2),(3)	Safety glass		IS 2553(Part 2)(Rev. 1):2019
101	(1)	Windscreen Wiper		NA
102	(1), (2)	Signaling devices, direction indicators and stop lights		NA
103	(1), (2)	Position of the indicator		-
104	(1)(v);(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 90.10 dB(A) / 97.1 dB(A)	IS 1884:1993
			Performance	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-1)Rev.1:2011
			Installation	AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2022 -2065 (IOCS: 164425)
Power Test Report No.	CTOEP 0710 dt. 20.04.2019, CT0PS 0390 dt. 07.03.2023
Horn Inst. Report No.	CTOCK 0417 dt. 20.02.2015, CT1VS 0558 dt. 28.03.2023

AUTORISED SIGNATORY				
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER				
				Page 2 of 3