



C	A	K	B	0091	F01
---	---	---	---	------	-----



Date : 12th June 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard		
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-		
94	(1), (2), (3)	Condition of tyres		-		
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004		
		Front/	90/90-12,64B 3.75-12 66E		JK Tyres, Apollo	
			90/90-12 64B 3.75-12 66B		Ceat	
		Rear	3.00-12, 63B, 90/90-12 54L		Ralson	
			90/90-12 54J 3.75-12 60J		TVS	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999		
99	-	Forward and backward motion		-		
100	(1),(2),(3)	Safety glass		IS 2553(Part 2)(Rev.1):2019		
101	(1)	Windscreen Wiper		NA		
102	(1), (2)	Signaling devices, direction indicators and stop lights		NA		
103	(1), (2)	Position of the indicator		-		
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005		
105	(1)(b), (3), (4), (5), (7)	Lamps		-		
106	(1)	Deflection of lights		-		
108	(1)	Use of red or white lights		-		
109	-	Parking lights		-		
110	-	Lamps for three wheelers		-		
111	-	Prohibition of spotlights etc.		-		
119	(1) & (2)	Horns	Installation	IS 15796:2008		
			Limit : 83 dB(A) to 112 dB(A)			
			Observed : 102 dB(A) / 104.4 dB(A) / 103.7			
			Performance	IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005		
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB		
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-1)Rev.1:2011		
			Installation	AIS-002 (Part-1)Rev.1:2011		

ICAT Ref No.	2022-2412 (IOCS: 165550)
Power Test Report No.	CT0PK 0152 dt. 21.04.2015
Horn Inst. Report No.	CTOCK 1138 dt. 30.06.2015, CT1VS 0431 dt. 11.03.2023, CT1VS 0432 dt. 11.03.2023

AUTHORISED SIGNATORY

	
MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR
	Page 2 of 3