



C A S B 0859

Date : 20<sup>th</sup> September 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2);(3), (4), (5) & (6) (Front / Rear - Tube Type)	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050:2004	
		4.50-10 8PR	Zahi Tyres		
		4.50-10 84E	Ralson		
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	4.50-10 85E	Brazã Tyres	IS 14664:2010	
		Brakes			
		Steering gear			
98	(1), (2) & (3)	Forward and backward motion		NA	
99	---	Safety glass		-	
100	(1), (2) & (3)	Windscreen wiper		IS 2553:1992 (Part 2)	
101	(1) & 2(iii)	Signaling devices, direction indicators and stop lights		IS 15802:2008	
102	(1), (2)	Position of the indicator		-	
103	(1) & (2)	Fitment of reflectors & Reflective tapes		AIS-057 (Rev. 1); 2010 & AIS:090:2005	
104	1(v) & (4)	Lamps		-	
105	(1)(b), (3),(4), (5) & (7)	Deflection of lights		-	
106	(1)	Use of red or white lights		-	
108	(1)	Parking Lights		-	
109	---	Lamps on 3 Wheelers		AIS-134:2016	
110	---	Prohibition of spotlights etc.		-	
111	-	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		98.7 dB(A)
120	(2)	Pass by Noise	Performance	IS 1884:1992	
			Limit :	77 dB(A)	
			Observed :	66 dB(A)	
ICAT Ref No.		2022-0303 (IOCS: 167008)			
Power Report No.		CTOPS 0858 dt. 02.08.2023			
Noise Report No.		CTOVS 1333 dt. 14.08.2023			
Horn Inst. Report No.		CTOVS 1334 dt. 14.08.2023			

AUTHORISED SIGNATORY



Saurabh Dalela (Signature)

VIKAS SADAN  
DEPUTY GENERAL MANAGER

SAURABH DALELA  
DIRECTOR

