



C	A	S	B	0859
---	---	---	---	------

Date : 25th September 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Front / Rear - Tube Type)	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050:2004	
		4.50-10 8PR	Zahi Tyres		
		4.50-10 84E	Ralson		
		4.50-10 85E	Braza Tyres		
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes		IS 14664:2010	
98	(1), (2) & (3)	Steering gear		NA	
99	---	Forward and backward motion		-	
100	(1), (2) & (3)	Safety glass		IS 2553:1992 (Part 2)	
101	(1) & 2(iii)	Windscreen wiper		IS 15802:2008	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	1(v) & (4)	Fitment of reflectors & Reflective tapes		AIS-057 (Rev. 1): 2010 & AIS:090-2005	
105	(1)(b), (3), (4), (5) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	---	Parking Lights		-	
110	---	Lamps on 3 Wheelers		AIS-134:2016	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		98.7 dB(A)
		Performance	IS 1884:1992		
120	(2)	Pass by Noise	Limit :	77 dB(A)	
			Observed :	66 dB(A)	

ICAT Ref No.	2022-0303 (IOCS: 167008)
Power Report No.	CTQPS 0858 dt. 02.08.2023
Noise Report No.	CTOVS 1333 dt. 14.08.2023
Horn Inst. Report No.	CTOVS 1334 dt. 14.08.2023

AUTHORISED SIGNATORY

		
VIKAS SADAN DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR	Page 2 of 4