






C	A	P	B	0092	F01
---	---	---	---	------	-----

Date : 28th September 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres	Make
			3.75-12, 66B / 90-90-12, 64B	CEAT
			3.75-12, 54L / 90-90-12, 54L	Ralson
			90-90-12, 64B	MRF
				IS 15627:2005 & AIS-050-2004
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3)	Safety glass		IS 2553(Part 2)(Rev.1):2019
101	(1)	Windscreen Wiper		IS 15802-2008
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	
			Limit :	83 dB(A) to 112 dB(A)
			Observed :	98.6 dB(A)
			Performance	IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-1)Rev.1:2011
			Installation	AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2022-2331 (IOCS: 165100)
Power Test Report No.	CT0PO 1248 dt 31.12.2019
Horn Inst. Report No.	CT0VP 0215 dt. 20.02.2020, CT1VS 1048 dt. 23.06.2023

AUTHORISED SIGNATORY				
VIKAS SADAN DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR			