






**C A Q N 0115 F01 V01**

**ANNEXURE - I**

**Date : 11<sup>th</sup> October 2023**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor vehicles width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Cross ply / tube)	Size & ply rating of tyres		IS-15636-2012, AIS-051:2004	
		Front	7.50 X 16 – 16PR (Single)		CEAT, Apollo, MRF
		Rear	7.50 X 16 – 16PR (Dual)		
96	(1), (2), (3), (4), (7)(a) & (8)	Brakes with ABS		IS 11852 : 2013	
98	(1), (2), (3) & (4)	Steering Gear		IS-12222:2011	
		Steering Effort		IS-11948:2010	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2) (Revision 1); 2019	
101	(1) & (2)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010, AIS 90:2019	
105	(1)(a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
114	(1)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(ii) & 18(ii)	Emission of smoke, vapour, etc. from motor vehicle (OBD II)		AIS-137 Part 4	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor(SLF)		AIS-018:2001	

<b>ICAT Ref No.</b>	2023-1168 (IOCS Ref: 169085)
<b>Engine Report No.</b>	CT0ER0334 dt. 18.08.2022 & CT0ER 0334 E01 dt:14.11.2022
<b>Noise Report No.</b>	CT0VQ 0123 dt. 04.02.2021 & CT0VS 0180 dt. 02.02.2023
<b>Horn Inst. Report No.</b>	ARAI/SHL/2019-2020/3000008997/TA/0223 dt: 15.11.2019

<b>AUTHORISED SIGNATORY</b>				
<b>VIKAS SADAN</b> <b>DEPUTY GENERAL MANAGER</b>	<b>SAURABH DALELA</b> <b>DIRECTOR</b>			