



C	A	R	B	0078	F01	V01
---	---	---	---	------	-----	-----

Date : 12th October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004
		Front/ Rear		90/90-12, 54L M/s RALCO	
		90/90-12, 54J M/s CEAT M/s TVS			
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signalling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	86.2 dB(A) / 84.4 dB(A)	
Performance					IS 1884:1993
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed	58 dB(A), 59 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
	(2)			Footrests	AIS 148:2018
	(4)			Stand	AIS 146:2018
	(5)			External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications Installation	AIS-001 (Part 2) (Rev.1):2011 AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-0574 (IOCS Ref: 167962)
Power Test Report No.	CTOES 0224 dt. 19.04.2023
Noise Report No.	CT0VQ 1515 dt. 21.12.2021, CT0VR 0588 dt. 25.04.2022
Horn Inst. Report No.	CT0VQ 1516 dt. 21.12.2021, CT1VS 1028 dt. 21.06.2023

AUTORISED SIGNATORY		INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY ICAT Innovation • Service • Excellence MANESAR	Signature	ICAT Logo
VIKAS SADAN DEPUTY GENERAL MANAGER				
SAURABH DALELA DIRECTOR				Page 2 of 4