



C A S B 0902

Date : 18th October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95 (1), (2), (3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050-2004
		90/90-12, 64B, 3.75-12, 66B	CEAT	
		90/90-12 54J, 3.75-12 60J	TVS	
		3.75-12, 66E	JK Tyre	
		3.75-12 66E	Apollo	
		3.75-12, 66B	Poddar	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3)	Safety glass		IS 2553(Part 2)(Rev. 1):2019
101	(1)	Windscreen Wiper		IS 15802-2008
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119 (1) & (2)	Horns	Installation		IS 15796:2008
		Limit :	83 dB(A) to 112 dB(A)	
		Observed :	95.6 dB(A)	
		Performance		IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125 (2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-1)Rev.1:2011
		Installation		AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2023-0451 (166190)
Power Test Report No.	CTOPS 0860 dt. 02.08.2023, CT0ES 0230 dt. 20.04.2023
Horn Inst. Report No.	CT0VS 1370 dt. 18.08.2023

AUTHORISED SIGNATORY			
VIKAS SADAN DEPUTY GENERAL MANAGER	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR *		
SAURABH DALELA DIRECTOR			Page 2 of 3