



C A S B 0903

Date : 18<sup>th</sup> October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres	Make	IS 15627:2005 & AIS-050-2004
			90/90-12,64B / 3.75-12, 66B	CEAT	
			90/90-12 54J	TVS	
			3.75-12, 66E	JK Tyre	
			3.75-12 66E	Apollo	
			3.75-12, 66B	Poddar	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3)	Safety glass		IS 2553(Part 2)(Rev.1):2019	
101	(1)	Windscreen Wiper		IS 15802-2008	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3),(4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	97.3 dB(A)	
			Performance		IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications		AIS-001 (Part-1)Rev.1:2011
		Mirror	Installation		AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2022-2333 (165213)
Power Test Report No.	CT0PS 0698 dt. 01.06.2023 & CT0ES 0230 dt. 20.04.2023
Horn Inst. Report No.	CT0VS 1161 dt. 18.07.2023

AUTHORISED SIGNATORY

<b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER	<b>INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY</b> Innovation • Service • Excellence * MANESAR *	<b>SAURABH DALELA</b> DIRECTOR	<b>Page 2 of 3</b>