



C A S B 0901

Date : 18th October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-
94	(1), (2), (3)	Condition of tyres			-
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres 3.75-12, 66 B	Make CEAT	IS 15627:2005 & AIS-050-2004
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999
99	-	Forward and backward motion			-
100	(1), (2), (3-A) & (3)(c)	Safety glass			IS 2553(Part 2)(Rev. 1):2019
101	(1)	Windscreen Wiper			IS 15802-2008
102	(1), (2)	Signaling devices, direction indicators and stop lights			-
103	(1), (2)	Position of the indicator			-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057-2005 & AIS-090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
109	-	Parking lights			-
110	-	Lamps for three wheelers			-
111	-	Prohibition of spotlights etc.			-
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	95.3 dB(A)	IS 1884:1993
Performance					
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-1)Rev.1:2011
			Installation		AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2022-2085; (IOCS: 164921)
Power Test Report No.	CTOPS 0642 dt. 03.05.2023, CT0ES 0165 dt. 25.03.2023
Horn Inst. Report No.	CT0VM 1991 dt. 28.11.2017

AUTHORISED SIGNATORY			
VIKAS SADAN =	INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence ★ MANESAR ★	Saurabh Dalela	Page 2 of 3
VIKAS SADAN DEPUTY GENERAL MANAGER		SAURABH DALELA DIRECTOR	