



**C A S B 0905**

**Date : 18<sup>th</sup> October 2023**

**ANNEXURE - I**

<b>Rule No.</b>	<b>Sub Rule(s)</b>	<b>Compliance Verified For</b>			<b>Standard</b>
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			
94	(1), (2), (3)	Condition of tyres			
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004
		Front/ Rear	90/90-12, 54J  3.75-12, 66B & 90/90-12, 54J	TVS  Ceat	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999
99	-	Forward and backward motion			-
100	(1), (2), (3)	Safety glass			NA
101	(1)	Windscreen Wiper			NA
102	(1), (2)	Signaling devices, direction indicators and stop lights			-
103	(1), (2)	Position of the indicator			-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps			
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
109	-	Parking lights			-
110	-	Lamps for three wheelers			-
111	-	Prohibition of spotlights etc.			-
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	89.8 dB(A)	
Performance			IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011
			Installation		AIS-002 (Part-2)Rev.1:2011

<b>ICAT Ref No.</b>	2023-0268 (167000)
<b>Power Test Report No.</b>	CT0PL 0323 dt. 17.05.2016
<b>Horn Inst. Report No.</b>	CTOLL 0806 dt. 02.08.2016

<b>AUTHORISED SIGNATORY</b>			
<b>VIKAS SADAN</b> =	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR *		
<b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER		<b>SAURABH DALELA</b> DIRECTOR	Page 2 of 3