







C A S B 0925

Date : 24th October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor vehicles width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Radial & tubeless)	Size & ply rating of tyres		IS-15636-2012, AIS-051:2004	
		Front (Single)	295/80 R22.5, 16PR		MRF JK Tyre
			295/80 R22.5, 18PR		CEAT Michelin
		Rear (Dual)	295/80 R22.5, 16PR		MRF JK Tyre
295/80 R22.5, 18PR	CEAT Michelin				
96	(1), (2), (3), (4), (7)(a) & (8)	Brakes		IS 11852 : 2013	
98	(1), (2), (3) & (4)	Steering Gear		IS-12222:2011	
		Steering Effort		IS-11948:2010	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3)(C)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019	
101	(1) & (2)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010, AIS 90:2019	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor		(Not applicable)	

ICAT Ref No.	2023 - 1081 (IOCS Ref: 170012)
Net Power Test Report No.	CT0ER 0392 dt. 06.10.2022
Noise Report No.	CT0VS 1652 dt. 13.10.2023
Horn Inst. Report No.	CT0VS 1650 dt. 13.10.2023

AUTHORISED SIGNATORY					
	VIKAS SADAN DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR			
					Page 2 of 6