







C A S B 0939

Date : 31st October 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2),(3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/	90/90-12,64B 3.75-12 66E		JK Tyres, Apollo
			3.75-12,66B		PODDAR TYRES
		Rear	3.75-12 66B,90/90-12 64B		Ceat
			3.75-12, 72B		Ralson
	90/90-12 54J 3.75-12 60J	TVS			
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1),(2),(3)	Safety glass		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		NA	
103	(1), (2)	Position of the indicator		-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		102 dB(A) / 104.4 dB(A) / 103.7
			Performance	IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-1)Rev.1:2011	
			Installation	AIS-002 (Part-1)Rev.1:2011	

ICAT Ref No.	2023 -0549 (IOCS: 167422)
Power Test Report No.	CT0PK 0152 dt. 21.04.2015
Horn Inst. Report No.	CTOCK 1138 dt. 30.06.2015, CT1VS 0431 dt. 11.03.2023, CT1VS 0432 dt. 11.03.2023

AUTHORISED SIGNATORY			
			
VIKAS SADAN DEPUTY GENERAL MANAGER		SAURABH DALELA DIRECTOR	Page 2 of 3