



C	A	S	B	0949
---	---	---	---	------

Date : 01<sup>st</sup> November 2023

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/	3.75-12, 66 B		CEAT
			3.75-12, 66 E		DOLFIN
		Rear	90/90-12, 54J		SPEEDWAYS
			90/90-12, 54J		RALSON
			3.75-12, 66 B		RALSON
90/90-12, 64 B	MRF				
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3)	Safety glass		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	91.5 dB(A)	
			Performance		IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref. Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications		AIS-001 (Part-2)Rev.1:2011
		Mirror	Installation		AIS-002 (Part-2)Rev.1:2011

ICAT Ref No.	2023-0758 (168508)
Power Test Report No.	CT0ER 0447 Dt.15.11.2022 & CT0PS 0968 Dt.21.09.2023
Horn Inst. Report No.	CT0VS 1718 dt. 25.10.2023

<b>AUTHORISED SIGNATORY</b>			
<b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER	<b>SAURABH DALELA</b> DIRECTOR	Page 2 of 3	