







C A P B 0665 V02

Date : 02<sup>nd</sup> November 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2) & (3)	Motor vehicles width, length & height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Radial & tubeless)	<b>Size &amp; ply rating of tyres</b>		IS-15636-2012, AIS-051:2004	
		Front	Single 245/70 R17.5 -14 PR 245/70 R17.5 -16 PR		Apollo / GEAT
			Rear		
96	(1), (2), (3), (4), (7)(a) & (8)	Brakes		IS 11852 : 2013	
98	(1), (2), (3) & (4)	Steering Gear		IS-12222:2011	
		Steering Effort		IS-11948:2010	
99		Forward and backward motion		-	
100	(1), (2), (3) & (3)(C)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019	
101	(1) & (2)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010, AIS 90:2019	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS-11827:2008	
118	(1)	Speed Governor		(Not applicable)	

<b>ICAT Ref No.</b>	2023 - 1375 (IOCS Ref: 170416)
<b>Net Power Test Report No.</b>	CT0ES 0058 dt. 01.02.2023
<b>Noise Report No.</b>	CT0VP 0946 dt. 07.12.2020
<b>Horn Inst. Report No.</b>	SHL/5/2016-2017/6861/2989 dt. 30.11.2016

<b>AUTHORISED SIGNATORY</b>			
 <b>VIKAS SADAN</b> DEPUTY GENERAL MANAGER	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR • 150700TAM	 <b>SAURABH DALELA</b> DIRECTOR	 Innovation • Service • Excellence
			Page 2 of 6