



C A S B 0963





Date : 03rd November 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & (2)	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless - Radial)	Front	145R12LT 86/84E8PR 145R12LT 86/84Q8PR	IS 15627:2005 & AIS-050:2004	
		Rear	M/s Ceat Ltd. M/s MRF Ltd.		
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	Brakes		IS 14664:2010	
98	(1), (2) & (3)	Steering gear		NA	
99	---	Forward and backward motion		-	
100	(1), (2), (3), (3c)	Safety glass		IS 2553: (Part 2) 2019	
101	(1)	Windscreen wiper		-	
102	(1) & (2)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1)(v) & (4)	Fitment of reflectors		AIS-057 (Rev. 1); 2010 & AIS:090-2005	
105	(1)(b), (3), (4), (5) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	---	Parking Lights		-	
110	---	Lamps on 3 Wheelers		AIS-134:2016	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		87 dB(A) to 112 dB(A)
			Observed :		93 dB(A)
			Performance	IS 1884:1993	
120	(2)	Pass by Noise	Limit :	77 dB(A)	
			Observed :	61 dB(A)	

ICAT Ref No. 2023-0655 (IOCS: 167415)
 Power Report No. CT0ES 0404 dt. 17.08.2023
 Noise Report No. CT1VS 1641 dt. 12.10.2023
 Horn Inst. Report No. ARAI/SHL/CT/APX-2021-25130/0540 dt. 16.02.2021

AUTHORISED SIGNATORY

 VIKAS SADAN DEPUTY GENERAL MANAGER	 Innovation • Service • Excellence MANESAR	 SAURABH DALELA DIRECTOR	 Page 2 of 4
---	---	---	--