







C	A	S	B	0993	Date : 24 th November 2023	
ANNEXURE - I						
Rule No.	Sub Rule(s)		Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)		Motor vehicle width, length and height		-	
94	(1), (2), (3)		Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres		Make	
			3.75-12, 66B		RALSON	
			3.75-12, 66B		CEAT Ltd.	
			3.75-12, 60J		TVS	
			3.75-12, 66E		MRF	
3.75-12, 66B		PODDAR TYRE		IS 15627:2005 & AIS-050-2004		
96	(1), (2), (3), (4)(i), (7)(b)		Brakes		IS 14664:1999	
99	-		Forward and backward motion		-	
100	(1), (2), (3)		Safety glass		NA	
101	(1)		Windscreen Wiper		NA	
102	(1), (2)		Signaling devices, direction indicators and stop lights		-	
103	(1), (2)		Position of the indicator		-	
104	(1)(v), (4)		Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3), (4), (5), (7)		Lamps		-	
106	(1)		Deflection of lights		-	
108	(1)		Use of red or white lights		-	
109	-		Parking lights		-	
110	-		Lamps for three wheelers		-	
111	-		Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation		IS 15796:2008	
			Limit :	83 dB(A) to 112 dB(A)		
			Observed :	100.2 dB(A)		
		Performance		IS 1884:1993		
122	(1) & (2)		Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-		Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-2)Rev.1:2011	
			Installation		AIS-002 (Part-2)Rev.1:2011	

ICAT Ref No.	2023-0481 (167481)		
Power Test Report No.	CT0ER 0499 dt. 08.12.2022 & CT0PS 0794 Dt. 06.07.2023		
Horn Inst. Report No.	CT0VS 1436 dt. 28.08.2022		
AUTHORISED SIGNATORY	 		
	 		
VIKAS SADAN DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR		Page 2 of 3