







C A N D 1002

Date : 30th November 2023

ANNEXURE - II

| Rule No. | Sub Rule(s) | Compliance Verified For | Standard | |
|--------------------------------------|--------------------------------------------|-----------------------------------------------------------|------------------------------------------------------|--------------------------------------------|
| 2 (b) | IS 14272: 2011 | Definitions – category of vehicle | A | |
| 93 | (1)(A)(X),1(B)(iv),2(d) | Motor Vehicle Width, Length and Height: | - | |
| 94 | (1), (2) & (3) | Condition of tyres | - | |
| 95-A | (1) & (2) | Size & ply rating of tyres for agricultural tractors | Make MRF/ Apollo / CEAT / Good year/ BKT | |
| | | Front 2W | | 6.00-16, 8PR |
| | | 4W | | 8.3-20, 6PR 8-18, 6PR (Optional) |
| | | Rear 2W | | 13.6-28, 12PR 14.9-28, 12 PR (Optional) |
| 4W | 14.9-28, 12 PR 13.6-28, 12PR (Optional) | | | |
| 96 | (1), (2), (7)(d), & (8) | Brakes | - | |
| 96-C | - | Brakes for agricultural tractor | IS:12061-1994 & IS:12207-2014 | |
| 98-B | (1), (2) & (3) | Steering Gears for agricultural tractors | IS:11859-2004 & AIS:042-2004 | |
| 99 | - | Forward and backward motion | - | |
| 100 | (1), (2), (3) & (3c) | Safety glass | NA | |
| 101 | (1) & (2) | Windscreen Wiper | NA | |
| 102 | (1) & (2) | Signaling devices, direction indicators and stop lights | - | |
| 103 | (1) & (2) | Position of the indicator | - | |
| 104-B | (1) & (2) | Fitment of reflectors for agricultural tractors | AIS-057 (Rev. 1): 2010 | |
| 105 | (1)(a), (2), (3), (4) & (7) | Lamps | - | |
| 106 | (1) | Deflection of lights | - | |
| 108 | - | Use of red or white lights | - | |
| 109 | - | Parking light | - | |
| 111 | - | Prohibition of spotlights etc. | - | |
| 114 | (1) | Exhaust gases and exhaust pipes | IS 12239 (Part 1):1996 | |
| 115 A | (9) | Emission of smoke, vapour, etc. from Agricultural Tractor | MoRTH/CMVR/TAP-115/116 | |
| 117 | (1) | Engine RPM-cum-hour Meter | - | |
| 119 | (1) & (2) | Horns | IS 1884:1992 | |
| 120 | (1) & (3) | Bystander Noise | AIS:115 (Part 1 & Part 2) - 2009 | |
| | | Limit (dB (A)) : Measured (dB (A)) : | | |
| | | 88 83 | | |
| | | Driver Perceived Noise Level | | |
| Limit (dB (A)) : Measured (dB (A)) : | | | | |
| 92 91 | | | | |

| | |
|--------------------|------------------------------------------------------------------------------------|
| ICAT Ref No. | 2023-1348 ; (IOCS NO. 169467) |
| Emission Cert. No. | ARAI/CMVR/(Ext-IV)AT(Trem III A)/Eicher- T III A S325 F2.4/2023-434 Dt. 31.08.2023 |
| Noise Report No. | CTOVS 1535 Dt. 15.09.2023 |

| | | | |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| AUTHORISED SIGNATORY | | | |
|  |  |  |  |
| VIKAS SADAN DEPUTY GENERAL MANAGER | | SAURABH DALELA DIRECTOR | Page 2 of 4 |