



**C | A | S | B | 1032**

**Date : 18<sup>th</sup> December 2023**

**ANNEXURE - I**

<b>Rule No.</b>	<b>Sub Rule(s)</b>	<b>Compliance Verified For</b>			<b>Standard</b>
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-
94	(1), (2), (3)	Condition of tyres			-
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004
		Front/ Rear	3.75-12, 66B	CEAT	
			3.75-12 66E	Ralson	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999
		Forward and backward motion			-
100	(1), (2), (3)	Safety glass			IS 2553(Part 2)(Rev.1):2019
101	(1)	Windscreen Wiper			IS 15802-2008
102	(1), (2)	Signaling devices, direction indicators and stop lights			-
103	(1), (2)	Position of the indicator			-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
109	-	Parking lights			-
110	-	Lamps for three wheelers			-
111	-	Prohibition of spotlights etc.			-
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	99.5 dB(A)	
Performance			IS 1884:1993		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-1)Rev.1:2011
			Installation		AIS-002 (Part-1)Rev.1:2011

<b>ICAT Ref No.</b>	2023-1484 (165673)
<b>Power Test Report No.</b>	CTOPS 0824 dt. 19.07.2023
<b>Horn Inst. Report No.</b>	CTOVS1897 dt. 01.12.2023

<b>AUTHORISED SIGNATORY</b>			
VIKAS SADAN =	INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR	SAURABH DALELA	Page 2 of 3
DEPUTY GENERAL MANAGER		DIRECTOR	