






| | | | | | |
|---|---|---|---|------|-----|
| C | A | S | B | 0991 | V01 |
|---|---|---|---|------|-----|

Date : 29th December 2023

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard | |
|----------|---|--|------------------|--------------------------------|---------|
| 93 | (1)(A), (1)(B), (2) & (4) | Motor Vehicle width, length and height | | - | |
| 94 | (1), (2) & (3) | Condition of tyres | | - | |
| 95 | (1), (2), (3), (4), (5), (6) & (7) (Radial & Tubeless) | Size & ply rating of tyres | | IS-15633:2005, AIS-051:2004 | |
| | | Front | 235/50 R19 103 V | | Pirelli |
| | | Rear | 255/45 R19 104 V | | |
| | Temp Tyre | T125 / 70 R19 101 M | Zhongce | AIS-110:2009 | |
| | (8) | Tyre pressure monitoring system | | AIS 154 : 2018 | |
| 96 | (1), (2), (3), 4(ii), (7)(a) & (8) | Brakes | | IS-15986:2015 | |
| | (4B) | Anti Lock Braking System (ABS) | | | |
| | (10) | Electronic Stability Control (ESC) | | AIS-133 :2016 | |
| | (11) | Brake assist System (BAS) | | AIS-152:2018 | |
| 96B | (a) & (b) | High Speed Brake Requirements | | IS-15986:2015 | |
| 98 | (3) | Steering gear | | IS-11948:2010 | |
| | (1), (2) | | | IS-12222:2011 | |
| 99 | - | Forward and backward motion | | - | |
| 100 | (1), (2), (3) & (3c) | Safety glass | | IS-2553 (Part 2):2019 | |
| 101 | (1) & (2) | Windscreen wiper | | IS-15804:2008 | |
| 102 | (1) & (2) | Signalling devices, direction indicators and stop lights | | - | |
| 103 | (1) & (2) | Position of the indicator | | - | |
| 104 | (1) & (4) | Fitment of reflectors | | AIS-057 (Rev. 1): 2010 | |
| 105 | (1) (a), (2), (3), (4) & (7) | Lamps | | - | |
| 106 | (1) | Deflection of lights | | - | |
| 108 | (1) | Use of red or white lights | | - | |
| 109 | - | Parking light | | - | |
| 111 | - | Prohibition of spotlights etc. | | - | |
| 115G | (1) & (2) | Fuel Consumption Standard | | - | |
| 117 | (1) & (2) | Speedometer | | IS-11827:2008 | |
| 118 | (1) | Speed Governor | | NA | |

| | |
|------------------------|------------------------------|
| ICAT Ref No. | 2023-1617 (IOCS Ref. 171700) |
| Motor Power Report No. | CT0ES 0065 Dt. 08.02.2023 |
| Noise Report No. | CT0VS 2028 Dt. 26.12.2023 |
| Horn Inst. Report No. | CT0VQ 0723 Dt. 07.07.2021 |

| AUTHORISED SIGNATORY | |
|---|--|
|  VIKAS SADAN DEPUTY GENERAL MANAGER |  SAURABH DALELA DIRECTOR |
| |  Page 2 of 6 |