





C	A	S	B	0709	V01
---	---	---	---	------	-----

Date : 29th December 2023

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard		
93	(1)(A), (1)(B) & 2	Motor vehicle width, length and height		-		
94	(1), (2) & (3)	Condition of tyres		-		
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004		
		Front	90/100-10, 53J		M/s MAXXIS M/s CEAT	
			Rear		90/100-10, 53J	M/s CEAT
			110/90-10, 61J		M/s MAXXIS	
96	(1), (2), (3),(4)(ib), (7)(c) & (8)	Brakes		IS 14664:2010		
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-		
103	(1)	Position of the indicator		-		
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010		
105	(1)(bb), (2)(i) & (4)	Lamps		-		
106	(1)	Deflection of lights		-		
108	(1)	Use of red or white lights		-		
111	-	Prohibition of spotlights etc.		-		
117	(1) & (2)	Speedometer		IS 11827:2008		
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008	
			Limit :	83 dB(A) to 112 dB(A)		
			Observed :	87 dB(A)		
			Performance		IS 1884:1993	
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998	
			Observed :	58 dB(A)		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005		
123	(1)	Safety devices in motor cycle	Pillion Handhold		IS 14495:1998	
	(2)		Footrests		AIS 148:2018	
	(4)		Stand		AIS 146:2018	
	(5)		External Projection		AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-		
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part 2) (Rev.1):2011	
			Installation		AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-1224 (IOCS Ref: 170492)
Power Test Report No.	CT0PS 0754 Dt. 22.06.2023
Noise Report No.	CT0VS 1179 dt. 21.07.2023
Horn Inst. Report No.	CT0VR 0607 dt. 29.04.2022

AUTHORISED SIGNATORY			
VIKAS SADAN DEPUTY GENERAL MANAGER	SAURABH DALELA DIRECTOR		