



C	A	Q	B	0959	F01
---	---	---	---	------	-----

Date : 12th February 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height			-
94	(1), (2), (3)	Condition of tyres			-
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050-2004
96	(1), (2), (3), (4)(i), (7)(b)	Brakes			IS 14664:1999
99	-	Forward and backward motion			-
100	(1), (2), (3)	Safety glass			IS 2553(Part 2)(Rev.1):2019
101	(1)	Windscreen Wiper			-
102	(1), (2)	Signaling devices, direction indicators and stop lights			-
103	(1), (2)	Position of the indicator			-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes			AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
109	-	Parking lights			-
110	-	Lamps for three wheelers			-
111	-	Prohibition of spotlights etc.			-
119	(1) & (2)	Horns	Installation		IS 15796:2008
			Limit :	83 dB(A) to 112 dB(A)	
			Observed :	94.7 dB(A)	IS 1884:1993
		Performance			
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065-2005
124	-	Safety standards of components as applicable			Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part-1)Rev.1:2011
			Installation		AIS-002 (Part-1)Rev.1:2011

ICAT Ref No.	2023- 1919 (173331)
Power Test Report No.	CT0PQ 0741 dt. 18.09.2021
Horn Inst. Report No.	CT0VQ 1253 dt. 14.10.2021

AUTORISED SIGNATORY			
JAYWANT HARDIKAR HEAD-CMVR	INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR	SAURABH DALELA DIRECTOR	Page 2 of 3