



CTOVT 1466

1QT8V9 1466

Date: 19 September 2024

SLD REPORT



1	Customer's Name	M/s MicroAutotech
2	Customer's Address	31, Patparganj Industrial Area, Delhi - 110 092
3	Description of test sample	Electronic Controlled Speed Limitation Device (Fly By Wire)
4	Test Objective	To carry out the performance test on the Speed Limitation Device (SLD), as installed on vehicle as per Cl. No. 5.7.3 of AIS-018 2001, upto Amendment No. 5, 2017.
5	Conclusion	Refer Test Results on page 2.
5.1	The Speed Limitation Device (SLD), specified in Sr. No. 3 of this test report with set speed of 80 km/h meets the specified requirements of Cl. No. 5.7.3 of AIS-018/2001, when installed on vehicle model: "TOYOTA INNOVA HYCROSS 7S BS-VI", M1 category of vehicle.	
6	Conformity of Production (CoP) Certificate :	CC0GS 7663 Dt. 12/10/2023
7	TAC Reference No. :	CE 0092 Dated - 20/01/2014

For more details of vehicle refer page no. 4 of 8 of this report.




CAUTION: TO BE OBSERVED BY THE TRANSPORT AUTHORITY



The tamper proofness of the SLD installation has been ensured, on the vehicle submitted for type approval. However the Transport Authorities are requested to verify and authenticate each and every vehicle model for sealing of Electronic Controlled Speed Limitation Device, Accelerator Pedal, etc. as shown in the Annexure I of this report. This is to safeguard against mechanical tampering of SLD. This has to be ensured for compliance at all the time. Individual transport authorities will have to evolve suitable mechanism for this proposal.

Remarks 1. Place of Issue : ICAT Centre II

ICAT Reference CCTNMICR7KVEL179923 Please turn over for DISCLAIMER

				
1466:19September2024M/sMicroAutotech31,PatparganjIndustrialArea,1466:19September	1466:19September2024M/sMicroAutotech31,PatparganjIndustrialArea,1466:19September	1466:19September2024M/sMicroAutotech31,PatparganjIndustrialArea,1466:19September	1466:19September2024M/sMicroAutotech31,PatparganjIndustrialArea,1466:19September	
Gavendra Singh Manager	Keshav Kr. Tripathi Asst. General Manager	Saurabh Dalela DIRECTOR	Page 1 of 8	