



C A R B 0973

Date : 23rd September 2022

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard					
93	(1)(A), 1(B), 2	Motor vehicle width, length and height								
94	(1), (2) & (3)	Condition of tyres								
95	(1), (2),(3), (4), (5) & (6) (Front / Rear - Tube Type)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004					
		4.5-10, 84E 8PR		M/s. Ralco						
96	(1), (2), (3), (4) (ia), (7)(b) & (8)	4.5-10, 85E 8PR		M/s. Zahi Tyres (Ceat) M/s Braza	IS 14664:2010					
		Brakes								
98	(1), (2) & (3)	Steering gear			NA					
99	--	Forward and backward motion								
100	(1), (2) & (3)	Safety glass			NA					
101	(1) & 2(iii)	Windscreen wiper			NA					
102	(1), (2)	Signaling devices, direction indicators and stop lights								
103	(1) & (2)	Position of the indicator								
104	1(v) & (4)	Fitment of reflectors & Reflective tapes			AIS-057 (Rev. 1): 2010 & AIS:090-2005					
105	(1)(b), (3),(4) & (7)	Lamps								
106	(1)	Deflection of lights								
108	(1)	Use of red or white lights								
109	--	Parking Lights								
110	--	Lamps on 3 Wheelers			AIS-134:2016					
111	-	Prohibition of spotlights etc.								
117	(1) & (2)	Speedometer			IS 11827:2008					
119	(1) & (2)	Horns	Installation (Below 7 Kw)		IS 15796:2008					
			Limit :	83 dB(A) to 112 dB(A)						
120	(2)	Pass by Noise	Observed :	101.7 dB(A)	IS 1884:1992					
			Performance							
ICAT Ref No.	2021-2180 (IOCS: 156510)									
	Power Report No.									
Noise Report No.		CTOPR 0502 dt. 29.03.2022								
Horn Inst. Report No.		CTOVR 0745 dt. 01.06.2022								
CTOVR 0746 dt. 01.06.2022										

AUTHORISED SIGNATORY

VIJAYANTA AHUJA DEPUTY GENERAL MANAGER	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY MANESAR		
		PAMELA TIKKU DIRECTOR (offg.)	Page 2 of 4