



| | | | | |
|---|---|---|---|------|
| C | A | M | D | 0993 |
|---|---|---|---|------|

Date : 27th September 2022

ANNEXURE - II

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard | |
|--------------------------------------|-----------------------------|---|--------------------------------------|---|----------------------------------|
| 93 | (1)(A)(X),1(B)(iv),2(d) | Motor Vehicle Width, Length and Height: | | - | |
| 94 | (1), (2) & (3) | Condition of tyres | | - | |
| 95-A | (1) & (2) | Size & ply rating of tyres for agricultural tractors | | Goodyear/ CEAT/Apollo/ MRF IS:13154-1991 | |
| | | Front | 6.00 x 16-8PR | | |
| | | Rear | 13.6 x 28, 12 PR | | |
| 96 | (1), (2), (7)(d), & (8) | Brakes | | - | |
| 96-C | - | Brakes for agricultural tractor | | IS:12061-1994 & IS:12207-2014 | |
| 98-B | (1), (2) & (3) | Steering Gears for agricultural tractors | | IS:11859-2004 & AIS:042-2004 | |
| 99 | - | Forward and backward motion | | - | |
| 101 | (1) & (2) | Windscreen Wiper | | NA | |
| 102 | (1) & (2) | Signaling devices, direction indicators and stop lights | | - | |
| 103 | (1) & (2) | Position of the indicator | | - | |
| 104-B | (1) & (2) | Fitment of reflectors for agricultural tractors | | AIS-057 (Rev. 1): 2010 | |
| 105 | (1)(a), (2), (3), (4) & (7) | Lamps | | - | |
| 106 | (1) | Deflection of lights | | - | |
| 108 | - | Use of red or white lights | | - | |
| 109 | - | Parking light | | - | |
| 111 | - | Prohibition of spotlights etc. | | - | |
| 114 | (1) | Exhaust gases and exhaust pipes | | IS 12239 (Part 1):1996 | |
| 115 A | (2), (3) & (7) | Emission of smoke, vapour, etc. from Agricultural Tractor | | - | |
| 117 | (1) | Speedometer | | - | |
| 119 | (1) & (2) | Horns | | IS 1884:1992 | |
| 120 | (1) & (3) | Silencers | Bystander Noise | | AIS:115 (Part 1 & Part 2) - 2009 |
| | | | Limit (dB (A)) : Measured (dB (A)) : | | |
| | | | 88 | 84 / 86 | |
| | | | Driver Perceived Noise Level | | |
| Limit (dB (A)) : Measured (dB (A)) : | | | | | |
| 92 | 91 | | | | |

| | |
|---------------------|---|
| ICAT Ref No. | 2022 - 1206 : (IOCS NO. 161157) |
| Emission Report No. | CORE 0293 Dt.12.03.2022 |
| Noise Report No. | CT0VK 0272 Dt. 29.06.2015 & CT0VM 0175 Dt. 11.02.2017 |

| | | | | |
|--|---|---|---|---|
| AUTHORISED SIGNATORY | |  |  |  |
| VIJAYANTA AHUJA DEPUTY GENERAL MANAGER | PAMELA TIKKU DIRECTOR (Offg.) | | | |