



**C | A | S | N | 0208**

Date : 24<sup>th</sup> February 2023

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For			Standard					
93	(1)(A), (1)(B) & (2)	Motor Vehicle width, length & height			-					
94	(1), (2) & (3)	Condition of tyres			-					
95	(1), (2), (3), (4), (5) & (6) (Cross ply / Radial, Tubeless)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004					
		Front	100/80-17 52 P	1. MRF 2. CEAT						
96	(1), (2), (3), (4(ib)), (4A), (7)(c) & (8)	Brakes with ABS			IS 14664:2010					
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights			-					
103	(1)	Position of the indicator			-					
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010					
105	(1)(bb), (2)(i) & (4)	Lamps			-					
106	(1)	Deflection of lights			-					
108	(1)	Use of red or white lights			-					
111	-	Prohibition of spotlights etc.			-					
114	(1) & (2)	Exhaust gases and exhaust pipes			-					
115	(1), (2)(i) & (19)(i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD II-A))			AIS-137					
117	(1) & (2)	Speedometer			IS 11827:2008					
119	(1) & (2)	Horns	Installation (Above 7kW)		IS 15796:2008					
			Limit :	87 dB(A) to 112 dB(A)						
			Observed :	100.7 / 98.9 / 100.8 dB(A)						
			Performance		IS 1884:1993					
120	(1)	Silencers			-					
	(2)	Pass by Noise	Limit :	77 dB(A) (80 < cc ≤ 175)	IS 3028:1998					
			Observed :	77 dB(A)						
122	(1) & (2)	Embossment of chassis number & engine number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005					
123	(1)	Pillion Hand Hold			IS 14495:1998					
	(2)	Footrest			AIS 148:2018					
	(4)	Stand			AIS 146:2018					
	(5)	External projection			AIS 147:2018					
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-					
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part 2) (Rev.1):2011					
			Installation		AIS-002 (Part 2) (Rev.1):2011					
<b>ICAT Ref No.</b>		(IOCS: 163556)								
<b>Emission Report No.</b>		Refer ANNEXURE - III								
<b>Noise Report No.</b>		CT0VP 0258 dt. 05.03.2020								
<b>Horn Inst. Report No.</b>		CT0VP 0258 dt. 05.03.2020								
<b>FTP Report No.</b>		CT0EP 0154 dt. 04.03.2020								
<b>AUTHORISED SIGNATORY</b>										
		 <b>INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY</b> <b>MANESAR</b> <i>Innovation • Service • Excellence</i>								
<b>MADHUSUDAN JOSHI</b> <b>DEPUTY GENERAL MANAGER</b>			<b>SAURABH DALELA</b> <b>DIRECTOR</b>							
										
Page 2 of 4										