



C A S B 0248

Date : 07<sup>th</sup> March 2023

## ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For			Standard
93	(1)(A), 1(B), 2	Motor vehicle width, length and height			-
94	(1), (2) & (3)	Condition of tyres			-
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Front/ Rear	Size & ply rating of tyres  3.00-10, 42J	Make  RALSON / CEAT / TVS	IS 15627:2005 & AIS-050:2004
96	(1), (2), (3), (4)(b), (7)(c) & (8)	Brakes with CBS			IS 14664:2010
102	(1), (2) & (3)	Signalling devices, direction indicators and stop lights			-
103	(1)	Position of the indicator			-
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010
105	(1)(bb), (2)(i) & (4)	Lamps			-
106	(1)	Deflection of lights			-
108	(1)	Use of red or white lights			-
111	-	Prohibition of spotlights etc.			-
117	(1) & (2)	Speedometer			IS 11827:2008
119	(1) & (2)	Horns	Installation (Below 7kW)  Limit : 83 dB(A) to 112 dB(A)  Observed : 89.9 dB(A)	Performance	IS 15796:2008  IS 1884:1993
120	(2)	Pass by Noise	Limit : 75 dB(A)  Observed 59 dB(A)		IS 3028:1998
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005
123	(1)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
	(2)			Footrests	AIS 148:2018
	(4)			Stand	AIS 146:2018
	(5)			External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-
125	(2)(a)	Rear View Mirror	Specifications  Installation		AIS-001 (Part 2) (Rev.1):2011  AIS-002 (Part 2) (Rev.1):2011

ICAT Ref No.	163385
Power Test Report No.	CT0PS 0289 dt. 03.02.2023
Noise Report No.	CT0VS 0358 dt. 02.03.2023
Horn Inst. Report No.	CT0VS 0353 dt. 02.03.2023

## AUTORISED SIGNATORY

MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER	 INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY Innovation • Service • Excellence MANESAR	SAURABH DALELA DIRECTOR	Page 2 of 4
--	---	----------------------------	-------------