



**C A O N** 0301 F01

Date : 06<sup>th</sup> April 2023

**ANNEXURE - I**

<b>Rule No.</b>	<b>Sub Rule(s)</b>	<b>Compliance Verified For</b>			<b>Standard</b>				
93	(1)(A), (1)(B) & (2)	Motor Vehicle width, length & height			-				
94	(1), (2) & (3)	Condition of tyres			-				
95	(1), (2), (3), (4), (5) & (6) (Cross ply/ Radial, Tubeless)	Size & ply rating of tyres		Make	IS 15627:2005 & AIS-050:2004				
		Front	100/80-17M/C 52P	MRF / CEAT					
96	(1), (2), (3), (4(ib)), (4A), (7)(c) & (8)	Brakes with ABS			IS 14664:2010				
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights			-				
103	(1)	Position of the indicator			-				
104	(1) & (4)	Fitment of reflectors			AIS-057 (Rev. 1): 2010				
105	(1)(bb), (2)(i) & (4)	Lamps			-				
106	(1)	Deflection of lights			-				
108	(1)	Use of red or white lights			-				
111	-	Prohibition of spotlights etc.			-				
114	(1) & (2)	Exhaust gases and exhaust pipes			-				
115	(1), (2)(i) & (19)(i)	Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (Including OBD II-A))			AIS-137				
117	(1) & (2)	Speedometer			IS 11827:2008				
119	(1) & (2)	Horns	Installation (Above 7kW)		IS 15796:2008				
			Limit :	87 dB(A) to 112 dB(A)					
			Observed :	94.3 dB(A)					
			Performance		IS 1884:1993				
120	(1)	Silencers			-				
	(2)	Pass by Noise	Limit :	77 dB(A) (80 < cc ≤ 175 cc)	IS 3028:1998				
			Observed :	68.4 dB(A)					
122	(1) & (2)	Embossment of chassis number & engine number & month of manufacture (Ref: Table 11 of the Technical Specifications)			AIS-065:2005				
123	(1)	Pillion Hand Hold			IS 14495:1998				
	(2)	Footrest			AIS 148:2018				
	(4)	Stand			AIS 146:2018				
	(5)	External projection			AIS 147:2018				
124	Refer Annexure-IA & IB	Safety standards of components as applicable			-				
125	(2)(a)	Rear View Mirror	Specifications		AIS-001 (Part 2) (Rev.1):2011				
			Installation		AIS-002 (Part 2) (Rev.1):2011				
<b>ICAT Ref No.</b>		(IOCS: 165326)							
<b>Emission Report No.</b>		CT0PS 0443 dt. 17.03.2023							
<b>Noise Report No.</b>		CT1VO 0941 dt. 18.09.2019							
<b>Horn Inst. Report No.</b>		CT0VO 0292 dt. 27.02.2019, CT0VO.0551 dt. 28.05.2019							
<b>FTP Report No.</b>		CT0EO 0383 dt. 23.11.2019							
<b>AUTHORISED SIGNATORY</b>									
<b>MADHUSUDAN JOSHI</b> <b>DEPUTY GENERAL MANAGER</b>			 <b>INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY</b> <b>MANESAR</b>		 Suzuki Service & Excellence				
<b>SAURABH DALELA</b> <b>DIRECTOR</b>									
Page 2 of 4									