



| | | | | | |
|----------|----------|----------|----------|-------------|------------|
| C | A | R | N | 0675 | V01 |
|----------|----------|----------|----------|-------------|------------|

Date : 25th April 2023

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard |
|----------|--|--|--------------------------|--|
| 93 | (1)(A), (1)(B), (2) & (3) | Motor Vehicle width, length and height | | - |
| 94 | (1), (2) & (3) | Condition of tyres | | - |
| 95 | (1), (1A), (2), (3), (4), (5) & (6) (Tubeless & Radial) | Size & ply rating of tyres | Make | IS-15633:2005, AIS-051:2004 AIS-142:2019 |
| | | Front / Rear / Spare | 145/80R13 75S JK Tyre | |
| | (8) | Tyre pressure monitoring system | | NA |
| 96 | (1), (2), (3), (4)(ii), (4B), (7)(a) & (8) | Brakes | | IS-15986:2015 |
| | (10) | Electronic Stability Control | | AIS-133:2016 |
| | (11) | Brake assist System | | AIS-152:2018 |
| 96B | (a) & (b) | High Speed Brake Requirements | | IS-15986:2015 |
| 98 | (3) | Steering gear | | IS-11948:2010 |
| | (1), (2) | | | IS-12222:2011 |
| 99 | - | Forward and backward motion | | - |
| 100 | (1), (2), (3) & (3c) | Safety glass | | IS 2553 (Part 2)(Rev.1) :2019 |
| 101 | (1) & (2) | Windscreen wiper | | IS-15804:2008 |
| 102 | (1) & (2) | Signalling devices, direction indicators and stop lights | | - |
| 103 | (1) & (2) | Position of the indicator | | - |
| 104 | (1) & (4) | Fitment of reflectors | | AIS-057 (Rev. 1): 2010 |
| 105 | (1) (a), (2), (3), (4) & (7) | Lamps | | - |
| 106 | (1) | Deflection of lights | | - |
| 108 | (1) | Use of red or white lights | | - |
| 109 | - | Parking light | | - |
| 111 | - | Prohibition of spotlights etc. | | - |
| 114 | (1) & (2) | Exhaust gases and exhaust pipes | | - |
| 115 | (1), (2)(i), 18(i) | Emission of smoke, vapour, etc. from motor vehicle | | AIS-137 |
| 115G | (1) & (2) | Fuel Consumption Standard | | AIS-137 |
| 117 | (1) & (2) | Speedometer | | IS-11827:2008 |
| 118 | (1) | Speed Governer (Only for Tour Variant) | | AIS-018:2001 |

| | |
|------------------------------|-------------------------------|
| ICAT Ref No. | 2022 - 2254 (IOCS No. 164600) |
| Emission Report No. | CT0PS 0582 dt. 06.04.2023 |
| Noise Report No. | CT0VR 0782 dt. 07.06.2022 |
| FTP Report No. | CT0ER 0262 dt. 22.06.2022 |
| Horn Inst. Report No. | CT0VR 0564 dt. 21.04.2022 |

AUTHORISED SIGNATORY

| | | |
|---|---|----------------|
|  MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER |  SAURABH DALELA DIRECTOR | Page 2 of 6 |
|---|---|----------------|