



C A R N 1209 V01

Date : 12th May 2023

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard | | |
|----------|---|---|---------------------------------|--|----------------|--------------|
| 93 | (1)(A), (1)(B), (2) & (3) | Motor Vehicle width, length and height | | - | | |
| 94 | (1), (2) & (3) | Condition of tyres | | - | | |
| 95 | (1), (1)(A), (2), (3), (4), (5) & (6) (Tubeless & Radial) | Size & ply rating of tyres | | IS-15633:2005, AIS 142:2019 & AIS-051:2004 | | |
| | | Make | 1. Ceat, India 2. MRF, India | | | |
| | (7) | Temporary Use Spare Wheel | 185/60 R16 89V & 195/60 R16 89H | 185/65R15 88R & 165/80R14 85R | 1. Ceat, India | AIS-110:2009 |
| | (8) | Tyre pressure monitoring system | | AIS 154 | | |
| 96 | (1), (2), (3), (4)(ii), (4B), (7)(a) & (8) | Brakes | | IS-15986:2015 | | |
| | (10) | Electronic Stability Control | | AIS 133:2016 | | |
| | (11) | Brake assist System | | AIS 152:2018 | | |
| 96B | (a) & (b) | High Speed Brake Requirements | | IS-15986:2015 | | |
| 98 | (3) | Steering gear | | IS-11948:2010 | | |
| | (1), (2) | | | IS-12222:2011 | | |
| 99 | - | Forward and backward motion | | - | | |
| 100 | (1), (2), (3) & (3c) | Safety glass | | IS 2553 (Part 2)(Rev.1) :2019 | | |
| 101 | (1) & (2) | Windscreen wiper | | IS-15804:2008 | | |
| 102 | (1) & (2) | Signalling devices, direction indicators and stop lights | | - | | |
| 103 | (1) & (2) | Position of the indicator | | - | | |
| 104 | (1) & (4) | Fitment of reflectors | | AIS-057 (Rev. 1): 2010 | | |
| 105 | (1) (a), (2), (3), (4) & (7) | Lamps | | - | | |
| 106 | (1) | Deflection of lights | | - | | |
| 108 | (1) | Use of red or white lights | | - | | |
| 109 | - | Parking light | | - | | |
| 111 | - | Prohibition of spotlights etc. | | - | | |
| 114 | (1) & (2) | Exhaust gases and exhaust pipes | | - | | |
| 115 | (1), (2)(i), 18(j) | Emission of smoke, vapour, etc. from motor vehicle (Bharat Stage - VI (OBD II)) | | AIS 137 | | |
| 115G | (1) & (2) | Fuel Consumption Standard | | AIS-137 | | |
| 117 | (1) & (2) | Speedometer | | IS-11827:2008 | | |
| 118 | (1) | Speed Governor | | NA | | |

| | |
|------------------------------|---|
| ICAT Ref No. | 2023-021 [IOCS No. 165770] |
| Emission Report No. | CT0PS 0645 dt. 09.05.2023 |
| Noise Report No. | CT0VR 1685 dt. 29.11.2022 |
| FTP Report No. | TA-2023 (Bharat Stage VI)/ELTR/2022-2023/369 dt. 27.09.2022 |
| Horn Inst. Report No. | CT0VP 0600 dt. 27.08.2020, CT1VQ 1532 dt. 22.12.2021 |

AUTHORISED SIGNATORY

| | | |
|---|-----------------------------------|-------------|
| | | |
| MADHUSUDAN JOSHI DEPUTY GENERAL MANAGER | SAURABH DALELA DIRECTOR | Page 2 of 6 |